Damaged lagging and poor duct connection


W2S4692 • W2 Snag (Sisk)

Project	2210 - Building S&T Bermondsey
Project no.	2210
Building	2210-JSS-ZZ-ZZ-M3-J-00001
Level	Level 00
Room	Meeting Room 4474
Coordinates	534569.35570 179026.16564 3.70000
Level Zones	Level 00

Work package	Main Contactor (SISK)
Workflow	Snagging - Sisk (WS2)
Date created	19 Oct 2026, 12:28
Deadline	-
Created by	Tom Jarvis, John Sisk and Son
Substitute for	Ahmad Hashimi, John Sisk and Son
Responsible	Ahmed Anwar, Kane Group Ltd

Cause	01 - Poor Workmanship
Caused By	Kane Group Ltd

Priority	Yellow
Estimated Rectification Cost	





19 Oct 2026, 12:28

Assigned to Kane Group Ltd


Created by	Tom Jarvis, John Sisk and Son
Substitute for	Ahmad Hashimi, John Sisk and Son
Assignee	Ahmed Anwar, Kane Group Ltd
Subject	Damaged lagging and poor duct connection

Damaged lagging and poor duct connection

W2S4692 • W2 Snag (Sisk)



1.1, 2026-10-19, 12.26



1.2, 2026-10-19, 12.26



1.3, 2026-10-19, 12.27