Duct lagging ensure sealed correctly under struts many gaps under block

W2S3559 • W2 Snag (Sisk)

Project	2210 - Building S&T Bermondsey
Project no.	2210
Building	2210-JSS-ZZ-ZZ-M3-J-00001
Level	Level Mezzanine
Room	Staff Welfare 4375
Coordinates	534583.82145 179023.67628 9.05000

Work package	Main Contactor (SISK)
Workflow	Snagging - Sisk (WS2)
Date created	18 Aug 2026, 16:13
Deadline	-
Created by	Lee Smith, John Sisk and Son
Substitute for	Ahmad Hashimi, John Sisk and Son
Responsible	Ahmed Anwar, Kane Group Ltd

Cause	09 - Other
Caused By	Kane Group Ltd

Priority	Red
Estimated Rectification Cost	



18 Aug 2026, 16:13

Assigned to Kane Group Ltd

Created by	Lee Smith, John Sisk and Son
Substitute for	Ahmad Hashimi, John Sisk and Son
Assignee	Ahmed Anwar, Kane Group Ltd
Subject	Duct lagging ensure sealed correctly under struts many gaps under block
Description	Duct lagging ensure sealed correctly under struts many gaps under block throughout areas

Duct lagging ensure sealed correctly under struts many gaps under block

W2S3559 • W2 Snag (Sisk)



1.1, 2026-08-18, 16.11



1.2, 2026-08-18, 16.11



1.3, 2026-08-18, 16.11



1.4, 2026-08-18, 16.11