Insulation pool extract duct incomplete/ insufficient ID’s

W2S4456 • W2 Snag (Sisk)

Project	2210 - Building S&T Bermondsey
Project no.	2210
Building	2210-JSS-ZZ-ZZ-M3-J-00001
Level	Level Mezzanine
Room	Corridor 5202
Coordinates	534559.83668 178996.79874 9.05000

Work package	Main Contactor (SISK)
Workflow	Snagging - Sisk (WS2)
Date created	5 Oct 2026, 12:15
Deadline	-
Created by	Lee Smith, John Sisk and Son
Substitute for	Ahmad Hashimi, John Sisk and Son
Responsible	Ahmed Anwar, Kane Group Ltd

Cause	09 - Other
Caused By	Kane Group Ltd

Priority	Red
Estimated Rectification Cost	





5 Oct 2026, 12:15

Assigned to Kane Group Ltd

Created by	Lee Smith, John Sisk and Son
Substitute for	Ahmad Hashimi, John Sisk and Son
Assignee	Ahmed Anwar, Kane Group Ltd
Subject	Insulation pool extract duct incomplete/ insufficient ID’s
Description	Insulation pool extract duct incomplete/ insufficient ID’s when passing through areas

Insulation pool extract duct incomplete/ insufficient ID’s

W2S4456 • W2 Snag (Sisk)



1.1, 2026-10-05, 12.11



1.2, 2026-10-05, 12.11



1.3, 2026-10-05, 12.11



1.4, 2026-10-05, 12.11

Insulation pool extract duct incomplete/ insufficient ID’s

W2S4456 • W2 Snag (Sisk)



1.5, 2026-10-05, 12.11